

**Pio Pico Energy Center  
Application for Certification  
11-AFC-1**

**Data Adequacy Requirements and Staff's Related Information Requests**

**ATTACHMENT I**

---



Existing view of the Route A transmission alignment from the north side of Calzada de la Fuente approximately 400 feet east of Alta Road. Calzada de la Fuente and the existing Otay Mesa Generating Project (south side of Calzada de la Fuente) are located in the foreground.

**FIGURE 3.7-3A**  
EXISTING VIEW FROM CALZADA  
DE LA FUENTE (ROUTE A)

**PIO PICO  
ENERGY CENTER**

PROJECT NO.: 29874827  
DATE: MARCH 2011

**URS**



Simulated view of the Route A transmission line from the north side of Calzada de la Fuente approximately 400 feet east of Alta Road. Calzada de la Fuente and the existing Otay Mesa Generating Project (south side of Calzada de la Fuente) are located in the foreground.

**FIGURE 3.7-3B**  
SIMULATED VIEW FROM CALZADA  
DE LA FUENTE (ROUTE A)

PIO PICO  
ENERGY CENTER

PROJECT NO.: 29874827  
DATE: MARCH 2011

**URS**





Existing view of the Route B transmission line alignment from the south side of Paseo de la Fuente, approximately 300 feet east of Alta Road. Paseo de la Fuente and the existing Otay Mesa Generating Project are located in the foreground.

**FIGURE 3.7-4A**  
**EXISTING VIEW FROM PASEO**  
**DE LA FUENTE (ROUTE B)**

**PIO PICO**  
**ENERGY CENTER**

PROJECT NO.: 29874827  
 DATE: MARCH 2011

**URS**



Simulated view of the Route B transmission line from the south side of Paseo de la Fuente, approximately 300 feet east of Alta Road. Paseo de la Fuente and the existing Otay Mesa Generating Project are located in the foreground.

**FIGURE 3.7-4B**  
SIMULATED VIEW FROM PASEO  
DE LA FUENTE (ROUTE B)

PIO PICO  
ENERGY CENTER

PROJECT NO.: 29874827  
DATE: MARCH 2011

**URS**